



ENAPART



93 S Railroad Avenue Unit C
Bergenfield NJ 07621 USA
www.enapart.com
sales@enapart.com



Via del Canneto 35,
Borgosatollo, Brescia - Italia
www.enapart.it
vendite@enapart.it



Barbaros Mah. Ihlamur Bul. Ağaoğlu
My Newwork No:3/15 Ataşehir / İstanbul
www.enapart.net
satis@enapart.net



PRIVADA 10 B SUR #3908 COL.
ANZUREZ, C.P. 72530, PUEBLA, PUE
www.enapart.com.mx
sales@enapart.com.mx



Friedrich-Ebert-Anlage 36, 60325
Frankfurt am Main, Germany
www.enapart.de
anfrage@enapart.de



4 boulevard Carnot, 95400
villiers-le-bel, Paris, France
www.enapart.fr
sales@enapart.fr



65049, ОДЕСА, ВУЛИЦЯ ІВАНА
ФРАНКА, БУДИНОК 55, ПОВЕРХ 3
www.enapart.com.ua
sales@enapart.com.ua



MUNICIPIUL BUCUREȘTI, SECTOR 3,
B-DUL BASARABIA, NR.250, CORP P+5
www.enapart.ro
sales@enapart.ro



〒584-0023 大阪府富田林市若松町
東2丁目2番16号
www.enapart.co.jp
sales@enapart.co.jp



PLAZA NUESTRA SEÑORA DE LAS
NIEVES 12 ,LOCAL ,50012,ZARAGOZA
www.enapart.es
ventas@enapart.es



Складова база „Онгъл“, Склад А2, п.к.
4006, гр. Пловдив, България
www.enapart.bg
sales@enapart.bg



3 Austin Mews, High Street, Hemel
Hempstead, HP1 3AF , United Kingdom
www.enapart.co.uk
sales@enapart.co.uk

Proxitron

Enapart always strives to provide the competitive prices and timings of supplies for its customers. We sell only original equipment and spare parts, although we are not always the official distributor or manufacturer's dealer. All displayed trademarks and part numbers are the property of their respective owners.

BRAND'S PRODUCTS

Product	Description
2021D	G Inductive proximity switch
2052N-5 IKN 070.05 G	inductive proximity switch
2052Q-5	Inductive Proximity Switch
Nr. 2065U Type IKQ 100T.38 GS4 (Teach)	Inductive proximity switch
2331H	Induktiver Analog-Sensor
2377C-5 IKL 015.05 GH	Inductive proximity switch
2446H IKU 021T.28 GS4	Inductive sensor strip
2451F, Type: IKU 031T.28 GS4 (Teach)	Inductive sensor strip
8032B	
8032B / FKM 230.13 GS4	Air flow monitor
8381BT	
9842J (ST 043/3-10PURH)	
8041A FKM 230.18 GS4	airflow monitor
IKM 070.33 G	inductive proximity switch
IKN 070.05 G 2 m Kabel	Induktiver Näherungsschalter
IKUD 031.28 G S4	Inductive Sensor Bar
LLK4	Fiber optic cable
MKK 050.194 S4 SA1	Analogue inductive sensor
OAA 703	Optics for fiber optic cables
OKS 7 T10.14 S9	Piro S Infrared Sensor
OSA 6747.13 G S5 / 6134Q	Piros infrared sensor
R5T285L383-003(1/4)-00-8HN34	
2474A (IDL 015.05 G.)	Inductive speed monitor
9848A	Inductive Sensor
2193B (IKU 341T.38 GS4)	Inductive area sensor
9841D (ST 041/4-2)	Connection cable
2451A (IKU 031.28 GS4)	Inductive sensor bar
2190G Type IKU 131T.38 G	inductive surface sensor
2092G Type IKU 251T.38 G	Inductive surface sensor
2049Q	Induktiver Näherungsschalter
2409E	Induktiver Näherungsschalter
2490A IKU 015T.28 GS4	Inductive sensor strip
8032B Type: FKM 230.13 G S4	airflow monitor
IKZ 475.33 GS4	Inductive proximity switch
IKZ 475.33 G S4 F / 2409F	Induktiver Näherungsschalter
ZSU A01.82	Drehzahlwächter

Product	Description
IKN 070.05 G 5 m Kabel	Induktiver Näherungsschalter
2229H-5	Induktiver Näherungsschalter
2319E	Induktiver Näherungsschalter
2319Q-5	Induktiver Näherungsschalter
2159M MKZ 120.59	Inductive Analogue Sensor
IKN 070T.38 GN S4 2050C	Inductive proximity switch
FKE 604.18 GS4 8382BT	
GS4 2451A	Inductive sensor strip
2409F	Inductive proximity switch
2409E Type: IKZ 475.33 G S4	Inductive proximity switch
IKZ 807.23 GH 2491B	
6410A	Piros Infrared Sensor
9816B HM 2	
9816B	articulated mounting foot
2451A	Inductive sensor strip
2491B	
IKK 050.38 GS4	inductive proximity switch
FKM 231.13 G S4 / 8043B	Air flow monitor
IKK 060.38 GS4	Inductive proximity switch
2452A	Inductive sensor bar
IKL 025.33 GHS4	Induktiver Näherungsschalter
ST041/4-5H	PP-Kabel
MKZ 120.59 (2159M)	
KKH 020.04 G	
ST 043/3-10PURH (9842J)	S4 Clutch
FKM 130.13 G (8008A-5)	
IKL 015.33 GH (2319D-10)	Inductive proximity switch
IKL015.33GH (23119D-15)	Inductive proximity switch
Art.Nr.: 2331F , Type: MKK 050.190 S4	Analog Inductive sensor
IPOH150.38 GS4	
FKM 230.13 G	
p/n 2052N Type IKN 070.05 G	Inductive proximity switch
2319D-5	
Type: IKN 070T.38 GS4 (Art. Nr.2049T)	Inductive Proximity Switch
Type: LLK 2 (Art. Nr. 6436F)	Fibre Optic Cable
IKM 070T.38 GS4	inductive proximity switch
ST 041/4-2	actuator
2319D	Inductive proximity switch
IKU 031.28 GS4 (2451A)	Inductive sensor bar
MKK 050.194 S4	Analog Inductive sensor
FKF 604.18 GS4	Flow sensor
2331G	
IKZ 807.23 GH5 (Art. 2491D)	Induktiver Näherungsschalter
2065S Type IKQR 100T.38 MG	Induktiver Näherungsschalter
6302B	

Product	Description
9850R	
9828R	
9861F	
LAB 201.5 L	
2002G-20 Type IKH 020.05 GH	Inductive proximity switch
FKEN 604.18 GS4	
2065W Type IKQA 100T.38 MG	Inductive proximity switch
5116A Type LTZ 185.28 GS4	light sensor
2319D-20	Inductive proximity switch
IKOH 101.05 GS5 (2060L)	Inductive proximity switch
6048A	Optics for optical cable LLK
6436F	fiber optic cable
FKM 230.12 GS4	airflow monitor
IKQ 100T.38 GS4	inductive proximity sensor
LSB 201.53 GLK	Piros disposable light barrier
2450D	Inductive proximity switch
2413B-15	Inductive proximity switch
IKZ 307.28 GH	Inductive proximity switch
2452G Type IKU 051T.28 GS4 L	Inductive Sensor Strip
IKL 015.33GH (2319D-15)	Inductive proximity switch
IKZ 301 28GH	Inductive proximity switch
IKZ 182.23 GH	Inductive proximity switch
OKA 704.05 G	Infrared-Sensor
IKU245.33G (Teil -Nr. 2091C)	Inductive surface sensor
IKU 031.28 G54	SENSOR STRIP
IKU 325T.38 GS4	Inductive area sensor
IKU 225.33G	Inductive area sensor
IKU231.33G	Inductive area sensor
2052Q	Inductive proximity switch
FKE 604.18 G Art. 8382AT	Flow-Sensor F6, G 1/2"
IKU 8101T.38 G S4	Inductive surface sensor
IKU 885T.38 G S4	Inductive surface sensor
9812A	Clamp
2374X-5, Type: IKZ 302.28 CG	Proximity Switch.
9841D, Type: ST 041/4-2	Angle coupling with 2 m cable
IKV 015.23 GS4	sensor
IKV 025.23 GS4	sensor
ST 041/3-2	Coupling with 2 m cable
FKF604.18GS4 /ecz	
2369A ZSU A01.82	Speed monitor
OKB 2047.18 G	Piros infrared sensor
IKLT 015.38 GH	inductive proximity switch
6920E	Piros S Infrared-Sensor / Pyrometer
9847B	female connector
6913E	Mounting unit adjustable

Product	Description
6913I	Interface cable and Software for OKS pyrometer
6450A	Piros Infrared-Sensor
6050A	Optic
9850J	female connector
9816D	Piros-Mounting Bracket
6913G	Laser pilot light attachment
9828H	Adapter M40 for mounting of accessory
9828A	Tubus
2369B ZSU A01.52	Speed monitor
2490C IKU 015T.28 GS4 L	Inductive sensor bar
IKOH 100T.38 GS4	Inductive proximity switch
IKL 015.33 GN	Inductive proximity switch
FKM 230.19	
ST 041/5-10 (9850H)	
6302C OXA 2029.3A GK S4	Piros infrared sensor
9850C ST 043/5-2	
9861F SIC 485U S6	Interface Converters
IKZ 475.38 GDV	inductive proximity switch
LAB 600.3 S4	
LSB 600.38 GV S4	
IKU 881T.38 G S4	Inductive surface sensor
6417A	sensor
IKU 051.28 GS4	
9816G	mounting bracket
9816I	mounting brackets
2046D-3	Inductive proximity switch
2046D-5	Inductive proximity switch
6036G / OAC 204 M	recording optics with LLK connection
2323A	Inductive proximity switch
2474D (IDL 010.05 G)	Inductive speed monitor
9614B	Extended connection cable
IKOA 120.38 GS4 / 2314C	Inductive proximity switch
6436I	fiber optic cable
9844B	S5 coupling
IKOA 120.38 GS4F / 2314F	Inductive proximity switch
2600B MXL 025.194 S4	Inductive analog sensor
2601B MXZ 475.194 S4	Inductive analog sensor
IKL 015.38 G S4	Inductive proximity switch
2374G-10	Inductive proximity switch
IKN 070.05G/2052N	Inductive proximity switch
8382AT Type: FKE 604.18 G	Flow-Sensor F6,
p/n: 6202E Type: OKA 0529.38 G S4	Piros infrared sensor
P/N: 2002P-5 Type: IKH 020.05 GH	inductive proximity switch
IKK060.38G	inductive sensor
IKQ 015.38G	INDUCTIVE SENSOR

Product	Description
IKQ 021.05 G	
OKB 2047.63 LK	
Nr.2377C-5 Type IKL 015.05 GH	inductive proximity switch
IKC 100.33 G	Inductive area sensor
Nr. 2065Z-5C Type IKQ 100T.38 G	Inductive proximity switch
MKZ 471.194 S4 / 2330F	Inductive analog sensor
MKH 035.19 S4	inductive analog sensor
2323P-5 (IKLT 020.05 GH1)	Inductive proximity switch
2354E IKQ 100.38 G S4	Inductive proximity switch
ST S5-DC/4-5 / 9844B	coupling
IKL 015.33 GHS4 / 2319G	inductive proximity switch
IKU 031T.28 GS4 L	Inductive sensor bar
5041A	Thru-beam sensor transmitter
5040C	Thru-beam sensor receiver
6049A	Optics for light guide cables LLK
FKF 704.86 G	Flow-Sensor F7, G 3/4"
2510A	inductive proximity switch
OXS 402T.2A G S8	INFRARED PYROMETER
ST S8-2	S8 (M12) coupling
SIC 485U 9861B	interface converter
ST S8 S4/5-2	connection cable
IKN 070T.38 GS4	Inductive proximity switch
Nr. 2377M Type IKL 015.04 GH1	inductive proximity switch
ST S9/5-2	coupling
IDL 015.28 G	Inductive speed monitor
MXK 050.194 H1 S4	inductive analog sensor
8032A	airflow monitor
IKOH 100.05 GS5	Inductive proximity sensor
MXK 060.194 S4	Inductive analog sensor
2510A IPN 105.38 G S4	inductive proximity sensor
ART-NR: 6410A-10 / TYPE OKA 204.05	Piros-Infrarot-Sensor
IKK 060.17 G	Inductive proximity sensor
IKK 060T.38 G	inductive proximity switch
2421F	
#0KB 2029.38 G S4 ART# 6204E	
TYPE #ST043/4-5H ART# 9842P	Coupling with PP cable
TYPE# HM 2 ART# 9816B	joint mounting foot
IKU 215T.38 G S4	Inductive area sensor
5200G	
9851K	
9855B	
9861E	
9828S	
ST 043/4-2	
9828R OL 35	

Product	Description
OKA 2029.38 G S4 (6204D)	Piros infrared sensor
OKB 2069.18 GLK	hot metal detector
LLAB 600.3 S4	
IKU 011T.28 G S4, P/N: 2405J	
IKU 021.28 G S4 , P/N: 2446C	
2465A /IKZ 122.23 GH3	inductive proximity switch
6204E	PHOTOCELL model Piros infrared sensor
IKK 060T.38 G S4	inductive proximity switch
2012V	
IKL 010.05G	inductive proximity switch
2481B / IKON 125.05 G S5	Inductive proximity switch
MKZ 471.19 S4 2330A	inductive analog sensor
2333D	
IKZ 301.23 GH4 / 2469B-10	inductive proximity switch
OKA 204.05 GS5	
LSA 201.53 GK	Piros one-way light barrier
OSA 6747.18 G	Infrared-Sensor
IKU 341.38 G S4	Inductive area sensor
OKA 203 33 G (6109A)	
2474A-10	inductive sensor
9828U	
2004D-5	
5038C	one-way photoelectric receiver,
5037E	one-way light barrier transmitter
LXUA 600.3A GV S8	Universal light barrier
9850N	
9853B	power supply
9851E	
2405G IKU 011.28 G S4	
IKL 015.33 GH (20m cable)	inductive proximity switch
IKOH 100.38 GS4	inductive proximity switch
IKUS 010.23 G S49	Inductive sensor strip
LMB 101	
ST S12-10S	
SIC 485UD	
KSS HJI 08	
KSV M20H	
KS KR 16/13	
6920E / OKS 4 GA13.14 S9	
9847B ST S9/5-2	coupling
6913B DAK 302	cooling jacket
6913E DAK 305	mounting angle adjustable
9999D	Test certificate for pyrometers
2503A IPK 080.38 G S4	
Art:2046F-5 -IKK 060T.38 G	

Product	Description
2029S	inductive proximity switch
6436L	fiber optic cable
IKL 010.33 GH 2434H-10	SENSOR, PROXIMITY
6410A-10 OKA 204.05 G	Infrared Sensor
IKC 235.38 G S4	inductive proximity switch
IKC 200.38 G S4	Inductive proximity switch